

# 12-IN-1 RESULTS COLOR CHART

NUANCIER DES RÉSULTATS 12-EN-1 / TABLA DE COLORES DE RESULTADOS 12 EN 1



	DOUCE/BLANDA SOFT		DURE/DURA HARD		TRÈS DURE/MUY DURA VERY HARD		
	0	25	50	120	250	425	
<b>1 Total Hardness</b> ppm Dureté totale Dureza total							
<b>2 Free Chlorine</b> ppm Chlore libre Cloro libre	0	1	2	3	4	5	
<b>3 Iron (Low Range)</b> ppm Fer (gamme basse) Hierro (gama baja)	0	0.1	0.5	1	5	10	
<b>4 Copper (Low Range)</b> ppm Cuivre (gamme basse) Cobre (gama baja)	0	0.5	1	3	10+		
<b>5 Nitrate</b> ppm Nitrate	0	10	25	50	100	250	500
<b>6 Nitrite</b> ppm Nitrite	0	1	5	10	20	40	80
<b>7 Calcium (High Range)</b> ppm Calcio (gamme élevé) Calcio (gama alta)	0	25	75	150	300		
<b>8 Total Chlorine</b> ppm Chlore total Cloro total	0	1	2	3	4	5	
<b>9 Fluoride (Low Range)</b> ppm Fluorure (gamme basse) Fluoruro (gama baja)	0	1	3	5	10	25	
<b>10 Total Alkalinity</b> ppm Alcalinité totale Alcalinidad total	0	40	80	120	180	240	
<b>11 Carbonate/Bicarbonate</b> ppm Carbonato/Bicarbonato	0	40	80	120	180	240	
<b>12 pH</b>	6.0	6.5	7.0	7.5	8.0	8.5	9.0



# Meets EPA limit / Respekte la limite de l'EPA / Cumple con el límite EPA  
 # Exceeds EPA limit / Dépasse la limite de l'EPA / Supera el límite EPA  
 # No EPA limit / N'a pas de limite de l'EPA / No tiene límite EPA  
 ppm parts per million / parties par million / partes por millón

◀ HANDLE / POIGNÉE / ASA

code below to