South East Water Scientific Services 3 Columbus Drive, Farnborough Hampshire, GU14 0NZ

E-Mail: sales@southeastwater.co.uk Website: www.southeastwater.co.uk



ANALYTICAL REPORT

Page 1 of 1

15/5003/

Certificate Number: Julia Coxon 1114033-1 Final

Order Number:

Swale Borough Council Environmental Services

Swale House, East Street

Sittingbourne

Kent **ME10 3HT**

Collected From: ARTESIAN WELL, CHURCH ROAD, OARE

Date Received: **Date Reported:** 21/06/2023 24/06/2023

Lab Ref.	Sample Details	Method	Test	Result		Units	Limit	Flag
4539664	Desc: ATESIAN WELL, CHURCH	400	E coli		0	mpn/100ml	0	
	ROAD, OARE	400	Total Coliforms		0	mpn/100ml	0	
	Collect From: ARTESIAN WELL, CHURCH ROAD, OARE Order No: 15/5003/	430	Colony Count 3 Days at 22°C		0	cfu/ml		
		430	Colony Count 2 Days at 37°C		0	cfu/ml		
	Received Date: 21/06/2023							
	Tested Date: 21/06/2023							
	Sampling Date: 21/06/2023 09:30							
	Sample Type: DW : Drinking Water							
	Product: SS-PWS							
	The sample was stored or transported at an	inapproriate tem	perature and as a result the test result(s) may	be invalid.				



Laboratory Manager

Disclaimers:

Unless otherwise stated, all results apply to the sample as received. Information provided by the customer (includes Date, Time, Sample Matrix & Sample Description) can affect the validity of the result.

Opinions and interpretations expressed in this report are outside the scope of UKAS accreditation.

Details of Uncertainty of Measurement and Analytical Quality Control are available on request.

Where a statement of conformity to a Regulatory Standard or customer limit is provided, the uncertainty of measurement is not taken into account unless shown on the certificate.

* - denotes non UKAS accredited test

A result of 0 cfu denotes none found in volume analysed

F - Result Exceeds The Maximum Pcv As Defined In The Private Water Supply Regulations (England)(Amendment) 2018

